HP 50g Connectivity Kit on Windows 10

Establishing USB connection

Step 1 – Download the Connectivity Kit

Download Link: http://www.hpcalc.org/hp49/pc/link/conn4x_english.exe

Step 2 – Install the Connectivity Kit

- Install the software downloaded in Step 1

Step 3 – Download the USB Drivers

- Download Link http://www.hpcalc.org/hp49/pc/link/hpcalculatorusbsetup.exe

Step 4 – Install the USB Drivers

- In Windows XP / Vista / 7 simply run the EXE file downloaded in Step 3 to install
- On Windows 8/8.1/10, the USB Drivers will not install until Driver Signature Enforcement has been disabled. To do so:
    1. Click the **Start** menu and select **Settings**.
    2. Click **Update and Security**.
    3. Click on **Recovery**.
    4. Click **Restart now** under **Advanced Startup**.
    5. Click **Troubleshoot**.
    6. Click **Advanced options**.
    7. Click **Startup Settings**.
    8. Click on **Restart**.
    9. The PC restarts, on the options screen pick **7) Disable driver signature enforcement**.
    10. Run the **hpcalculatorusbsetup.exe** file downloaded in Step 3 to install the USB drivers. NOTE: You will get a warning that Windows can't verify the publisher of the software, you must choose "Install this driver software anyway"

Step 5 – Open the Connectivity Kit and Connect

- **File > Connect** – See the Connectivity Help for more information on how to connect